

www.monobind.com

100 North Pointe Drive Lake Forest, CA 92630 TEL 949.951.2665 FAX 949.951.3539

## **Advisory Notice**

Date Released: 2022-April-18
Posted By: Quality Assurance

Reagents Affected: Any Reagent with White Cap; Including Calibrators, Controls, Enzymes, Biotin,

Buffer, Neutralizing Buffer, Releasing Reagent,

Brief Description: Cap Color Change due to Supply Delay/ Shortage

White to Silver/ Gray

Due to covid-related supply delays from the manufacturer, Monobind has diminished its inventory of <u>White Polypropylene (PP) Caps</u>. Monobind has sourced an alternative <u>Silver/ Gray PP Caps</u> from the same manufacturer which will be used as a replacement.

Please note: This change is only cosmetic, there is no impact on product performance. Monobind is making all efforts to return to white PP caps as soon as possible. The manufacture has indicated that white caps will be available at the end of the month (April 2022). Therefore, this will change will not be long lasting.

Thank you for your understanding as the pandemic has created extraordinary and often unpredictable delays in the supply chain.

## In Summary:

Affected Reagent	Change	Effective
With White Caps		
Calibrators	White PP Caps to Silver/ Gray PP	Immediately
Controls	White PP Caps to Silver/ Gray PP	Immediately
Enzymes	White PP Caps to Silver/ Gray PP	Immediately
Biotins	White PP Caps to Silver/ Gray PP	Immediately
Buffer	White PP Caps to Silver/ Gray PP	Immediately
Neutralizing Buffer	White PP Caps to Silver/ Gray PP	Immediately
Releasing Reagent	White PP Caps to Silver/ Gray PP	Immediately

As an official of the company, I verify this information to be true and correct.

Sincerely,

AShatola

Anthony Shatola
Quality Assurance Director